Maryland Historical Trust State Historic Sites Inventory Form MARYLAND INVENTORY OF HISTORIC PROPERTIES Form

Survey	No.	B-4412
sur ve y	NO.	B-4412

Magi No.

. DOE __yes __no

1. Nam	e (indicate pre	ferred name)		
historic	319 West	Franklin Street		
and/or common	Stew/Arts	Trader of Fine	Furniture	٠
2. Loca	ation			
street & number	319 W. Fr	anklin Street		_ not for publication
city, town	Baltimore	vicinity of	congressional district	Seventh
state	Maryland	county	Baltimore	
	sification	<u> </u>		
Category district X building(s) structure site object	Ownership public private both Public Acquisition in process being considered X_ not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Useagriculture Xcommercialeducationalentertainmentgovernmentindustrialmilitary	museum park private residence religious scientific transportation other:
4. Own	er of Proper	ty (give names a	nd mailing addresses	of <u>all</u> owners)
name	Toula and	Olga Kritikos		72
street & number	319 W. Fr	anklin Street	telephone no	.:
city, town	Baltimore		MD 21:	
5. Loca	ation of Lega	al Description	on	
courthouse, regis	stry of deedsBadtimore	City Courthous	e	RHB3452
street & number	100 N. Ca	lvert Street, R	oom 610	folig92
city, town	Baltimore		state	MD
6. Rep	esentation	in Existing	Historical Surve	eys
title				
date			federal state	county loc
ository for su	rvey records			
city, town			state	

7	ne	SC	PIR	 an
	UC	-3L	IIN	VII

Survey No. B-4412

Condition excellent goodX fair	deteriorated ruins unexposed	Check one unaltered altered	Check one original site moved date of	move	
--------------------------------	------------------------------	-----------------------------	---------------------------------------	------	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Resource Count: 1

This circa 1850 commercial building faces north on W. Mulberry Street and abuts a partywall structure to the east and an alley inlet to the west. The brick building is three stories high and three bays wide with a gable roof. The brick facade has been covered in circa 1960s formstone. The street frontage is 25' and the depth is 116'4".

The first story has four bays containing a window, entrance door, window, and secondary door that appears to lead to the upper stories' stairhall. The windows are small display windows set above a black striated vitrolite glass foundation wall. Silver tape outlines borders around the perimeter of the window panes. The door in the second bay opens on to the first-story commercial space. The entrance has curved, bullnose glass block jambs. The transom is boarded up. The door in the fourth bay is a solid panel door with blocked transom. The formstone is applied in fake key stone lintels over the openings.

The second and third stories have three 1/1 sash windows with formstone sills and lintels with voussoirs. The second story windows were originally taller than those on the third, but the height difference has been obliterated by infill panels.

The original cornice is covered by an aluminum boxed cornice. Chimney stacks rise above the gable roof along the east wall. The west wall is blank and parged.

The interior is finished with wallboard and a suspended acoustic tile ceiling.

0. 3	significance	Survey No.	B-4412
1600	D-1499archeology-historicconservation D-1599agricultureeconomics D-1699architectureeducation D-1799artengineering D-1899commerceexploration/settle	ow ning landscape architect law literature military music ement philosophy politics/government	science sculpture social/ humanitarian theater
Specific	dates Builder/Architect	unknown	
check:	Applicable Criteria: A B XC D and/or Applicable Exception: A B C D	EFG	
	Level of Significance:nationalstat	e X_local	
Prepare	both a summary paragraph of significance a	ind a general statement	of history and

support.

The architectural design of this three-story, three-bay building is probably an example of a circa 1860 combination commercial-residential building. The first story would have been used for sales or display area and the upper stories could have been used as offices or as residential quarters. Architectural historian Richard Longstreth writes that "the gradual abandonment of the shop-house as the dominant form of commercial architecture was due to the ever-increasing demands for trade and professional services along with a corresponding increase in land values, all of which fostered the design of buildings used entirely for commercial purposes."1 In this case the commercial requirements could be met by modifying the first story and inserting plate glass windows. The separate entrances for the lower and upper stories reiterates the segregation of tenants and activities in the building. building type attests to the mixed commercial and residential character of the neighborhood at the mid-century mark.

Several twentieth-century alterations express the ongoing commercialization of the neighborhood. The vitrolite glass and curved glass block door jambs date to the 1930s. The formstone veneer is an example of urban architectural renewal--Baltimore 1960s style.

¹ Longstreth, The Buildings of Main Street, pp. 24,29.

9. Major Bibliographical References

Survey No.

B-4412

Richard Longstreth, The Buildings of Main Street (Washington: Preservation Press, 1987).

10. Geographic	al Data		
Acreage of nominated property Quadrangle name Baltimo UTM References do NOT comp1	re East Qua		Quadrangle scale
Zone Easting North	لبلبل	Zone Easting	Northing
		P	
		apping state or county bo	undaries
List all states and counties for		apping state or county bo	undaries code
List all states and counties for state	properties overl		
List all states and counties for state	properties overl code code	county	code
List all states and counties for state state	code code	county	code
List all states and counties for state State 11. Form Preparame/title Diane Shaw, Are	code code code code code code	county county Historian	code
	code code code code code code	county county Historian date	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST
DHCP/DHCD
100 COMMUNITY PLACE
CROWNSVILLE, MD 21032-2023
301-514-7600

COMPREHENSIVE PLAN DATA

HISTORIC CONTEXT:

Geographic Organization:
Piedmont

Chronological/Developmental Period:

Agricultural-Industrial Transition, 1815-1870

Modern Period, 1930-present

Historic Period Themes:
Architecture
Economics

Resource Type:
Building

Historic Environment: Urban

Historic Function and Use:

Residential

Known Design Source: None

REVISIONS Let 3/4 DIV PERDRED C.SH. 9830 LOT 21/35 PER O.O.; C.SH. 77-044 Lots 5/6 & T Cor Per Deeds; C.SH. 81-254.

(530/548)

ST. W. FRANKLIN 8 40 9 15 10/11 39 0.273 Ac. 38 12 37 121'6" 36 13 PIERCE 20, ST. 14 205-14 152 644 15 21/35 16 17 18 19 STATE 20

(563)

ST.

W. MULBERRY

(57.7)

NOTICE

ST.

THIS IS A REAL PROPERTY PLAT AS PROVIDED FOR UNDER ARTICLE 76(d) OF THE CITY CHARTER IT IS COMPILED FROM TITLE AND OTHER SOURCES AND IS NOT AN AUTHENTIC SURVEY.

CITY OF BALTIMORE
DEPARTMENT OF PUBLIC WORKS

PROPERTY LOCATION DIVISION


ward 4 section 2 BLOCK 562

SCALE 1-50" DATE NOV. 1966

CED BY P.W.

N. EUTAW

B-4412 Stew/Arts Trader of Fine Furniture 319 W. Franklin Street Block 0562 Lot 001 Baltimore City





3-4412 319 W. Franklin St. Baltimore MD Drane Shaw 8/91 Maryland SHPO Facade, north elevation